

Anderson Pools and Spas Concrete Disclaimer

After a long and successful career in concrete construction starting in 1955 long before our first pool was built in 1983, we must face the fact that in spite of every advance in concrete technology and sixty years of practice we must concede that there is no physical way to completely eliminate random cracking in concrete slabs whether in Concrete Driveways or Pool decks. We reinforce all slabs with rebar, use 4000 psi concrete and never backfill with dirt. We only backfill with washed crushed stone and compact it to limit settling. Random cracking has never been a big problem for us but some is inevitable and is not warranted under this proposal.